

SAP Technical Upgrade ECC 6.0

Training Manuals



IMAGINATION BEYOND EDGES

Task List

Plant Maintenance

Prepared by : Usman Nazir


Date of Publication : 29.07.2011



Procedure

1. Start the transaction using the menu path or transaction code.

SAP Easy Access



2. Click Logistics tree item ▶ **Logistics**.
3. Click Plant Maintenance tree item ▶ **Plant Maintenance**.
4. Click Preventive Maintenance tree item ▶ **Preventive Maintenance**.
5. Click Work Scheduling tree item ▶ **Work Scheduling**.
6. Click Task Lists tree item ▶ **Task Lists**.
7. Click For Equipment tree item ▶ **For Equipment**.
8. Double-click IA01 - Create tree item **IA01 - Create**.



Create Equipment Task List: Initial Screen

Equipment task list Edit Goto Settings Environment System Help

Equipment task list: 10014084

Task list

Equipment: 10014084

User defaults

Profile:

Change Number:

Key date: 01.08.2011

U IBM PKGDVP INS

9. Press "Return".



Create Equipment Task List: Header General View

Equipment task list Edit Goto Task list header Extras Environment System Help

Create Equipment Task List: Header General View

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton

Group 300447
Group Counter 1 Training Material for Carton
Planning plant 0040

Assignments to Header

Work center LEHM / 0040 LEMANIC MAINTENANCE
Usage
Planner group
Status ☒
System Condition
Maintenance strategy
Assembly
☐ Deletion flag

OM Data

Inspection points
Ext. numbering Unique external numbering possible

U IBM PKGDVP INS

10. As required, complete/review the following fields:

Field	R/O/C	Description
Status	R	Example:

11. Press "F4".



Status (1) 4 Entries found

Status (1) 4 Entries found	
Restrictions	
St...	Description of the stat...
1	Created
2	Released for order
3	Released for costing
4	Released (general)

12. Double-click label

4	Released (general)
---	--------------------



Create Equipment Task List: Header General View

Equipment task list Edit Goto Task list header Extras Environment System Help

Create Equipment Task List: Header General View

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton

Group 300447
Group Counter 1 Training Material for Carton
Planning plant 0040

Assignments to Header

Work center LEHM / 0040 LEMANIC MAINTENANCE
Usage
Planner group
Status 4
System Condition
Maintenance strategy
Assembly
☐ Deletion flag

OM Data

Inspection points
Ext. numbering Unique external numbering possible

U IBM PKGDVP INS


13. As required, complete/review the following fields:

Field	R/O/C	Description
System Condition	R	Example:

14. Press "F4".



Syst.Condition (1) 2 Entries found



15. Double-click label

1 in operation



Create Equipment Task List: Header General View

Equipment task list Edit Goto Task list header Extras Environment System Help

Create Equipment Task List: Header General View

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton

Group 300447
Group Counter 1 Training Material for Carton
Planning plant 0040

Assignments to Header

Work center LEHM / 0040 LEMANIC MAINTENANCE
Usage
Planner group
Status 4
System Condition 1
Maintenance strategy
Assembly
☐ Deletion flag

OM Data

Inspection points
Ext. numbering Unique external numbering possible

U IBM PKGDVP INS

16. As required, complete/review the following fields:

Field	R/O/C	Description
Maintenance strategy	R	Example:

17. Press "F4".



Maintenance strategy (1) 7 Entries found

Maintenance strategy (1) 7 Entries found				
Restrictions				
Strat.	StratD.	S	Un	Cal
A	Scheduling by calendar		MON	
B	Scheduling by key date	1	MON	01
C	Scheduling by factory calendar	2	DAY	01
D	Performance-based sched. (KM)	3	KM	
DAYS	Scheduling by factory calendar	2	DAY	PL
DPP	Diesel Power Plant	3	HR	PL
STNDRD	Standard Time-Based Maint.	2	DAY	PL



18. Double-click label

STNDRD Standard Time-Based Maint. 2 DAY PL

Create Equipment Task List: Header General View

19. As required, complete/review the following fields:

Field	R/O/C	Description
Usage	R	Example:

20. Press "F4".



Task list usage (1) 9 Entries found

Task list usage (1) 9 Entries found	
Restrictions	
Usage	Description
1	Production
2	Engineering/design
3	Universal
4	Plant maintenance
5	Goods receipt
51	Goods receipt model
53	GR external process.
6	Goods issue
9	Material check
9 Entries found	

21. Double-click label 4 Plant maintenance .



Create Equipment Task List: Header General View

Equipment task list Edit Goto Task list header Extras Environment System Help

Create Equipment Task List: Header General View

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton

Group 300447
Group Counter 1 Training Material for Carton
Planning plant 0040

Assignments to Header


Work center LEHM / 0040 LEMANIC MAINTENANCE
Usage 4
Planner group
Status 4
System Condition 1
Maintenance strategy STNDRD
Assembly
☐ Deletion flag

OM Data

Inspection points
Ext. numbering Unique external numbering possible

U IBM PKGDVP INS

22. Press "Return".

23. Click Operation button .



Create Equipment Task List Operation Overview

Equipment task list Edit Goto Operation Extras Environment System Help

Create Equipment Task List Operation Overview

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton Grp.Countr 1

General Operation Overview

OpAc	SOp	Work ctr	Print	Ctrl	Operation Description	LT Work	Un.	No.	Duration	Un.	C Pct	Int. distr	Fac	ActTyp	StText&ly	Assembly	TT	WG	WT	Q	L	C	OrdQuantity	Unit	Net Price	Crcy	U
0010	LEMM	0040	PM01			☐																	1			PKR	
0020	LEMM	0040	PM01			☐																	1			PKR	
0030	LEMM	0040	PM01			☐																	1			PKR	
0040	LEMM	0040	PM01			☐																	1			PKR	
0050	LEMM	0040	PM01			☐																	1			PKR	
0060	LEMM	0040	PM01			☐																	1			PKR	
0070	LEMM	0040	PM01			☐																	1			PKR	
0080	LEMM	0040	PM01			☐																	1			PKR	
0090	LEMM	0040	PM01			☐																	1			PKR	
0100	LEMM	0040	PM01			☐																	1			PKR	
0110	LEMM	0040	PM01			☐																	1			PKR	
0120	LEMM	0040	PM01			☐																	1			PKR	
0130	LEMM	0040	PM01			☐																	1			PKR	
0140	LEMM	0040	PM01			☐																	1			PKR	
0150	LEMM	0040	PM01			☐																	1			PKR	
0160	LEMM	0040	PM01			☐																	1			PKR	
0170	LEMM	0040	PM01			☐																	1			PKR	
0180	LEMM	0040	PM01			☐																	1			PKR	
0190	LEMM	0040	PM01			☐																	1			PKR	
0200	LEMM	0040	PM01			☐																	1			PKR	
0210	LEMM	0040	PM01			☐																	1			PKR	
0220	LEMM	0040	PM01			☐																	1			PKR	
0230	LEMM	0040	PM01			☐																	1			PKR	

MntPack Components Rel PRT SPack Insp.Chair Entry 0 / 0

U IBM PKGDVP INS

24. As required, complete/review the following fields:

Field	R/O/C	Description
Operation Description	R	Example:
Operation Description	R	Example: Oilling
Work	R	Example:
Work	R	Example: 1



Field	R/O/C	Description
Un.	R	Example:
Un.	R	Example: HR
Operation Description	R	Example: Re Fueling
Work	R	Example: ,5
Un.	R	Example: hr

25. Click list item

0010	LEMM	0040 PM01 Drilling	1,0	HR					1	LABOUR					1			PKR	
------	------	--------------------	-----	----	--	--	--	--	---	--------	--	--	--	--	---	--	--	-----	--

26. Click list item

0020	LEMM	0040 PM01 Re Fueling	0,5	HR					1	LABOUR					1			PKR	
------	------	----------------------	-----	----	--	--	--	--	---	--------	--	--	--	--	---	--	--	-----	--

27. Click MntPack button MntPack.



Create Equipment Task List: Maintenance Package Overview

Task list Edit Goto Operation Extras Environment System Help

Create Equipment Task List: Maintenance Package Overview

Maintenance package Internal External Header Task list

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton Grp.Countr 1

Operat. Overview Maint. Packages																		
Op.	SOp	Operation Description	1D	2D	3D	1W	2W	3W	4W	5W	6W	7W	2M	3M	4M	6M	9M	1Y
0010		Oiling	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐
0020		Re Fueling	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐	☐

Components Rel PRT Insp.Char Entry 1 / 2

U IBM PKGDVP INS

28. Click 1W / 0010 check box .
29. Click 4W / 0020 check box .
30. Click button .



Create Equipment Task List Operation Overview

Equipment task list Edit Goto Operation Extras Environment System Help

Create Equipment Task List Operation Overview

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton Grp.Countr 1

General Operation Overview

OpAc	Sop	Work ctr	Print	Ctrl	Operation Description	LT	Work	Un	No	Duration	Un	C	Pct	Int	distr	Fac	ActTyp	StText	ky	Assembly	TT	WG	WT	O	L	C	OrdQuantity	Unit	Net Price	Crcy	Pl	
0010	LEMM	0040	PM01		Oiling		1,0	HR								1	LABOUR										1				PKR	
0020	LEMM	0040	PM01		Re Fueling		0,5	HR								1	LABOUR										1				PKR	
0030	LEMM	0040	PM01																								1				PKR	
0040	LEMM	0040	PM01																								1				PKR	
0050	LEMM	0040	PM01																								1				PKR	
0060	LEMM	0040	PM01																								1				PKR	
0070	LEMM	0040	PM01																								1				PKR	
0080	LEMM	0040	PM01																								1				PKR	
0090	LEMM	0040	PM01																								1				PKR	
0100	LEMM	0040	PM01																								1				PKR	
0110	LEMM	0040	PM01																								1				PKR	
0120	LEMM	0040	PM01																								1				PKR	
0130	LEMM	0040	PM01																								1				PKR	
0140	LEMM	0040	PM01																								1				PKR	
0150	LEMM	0040	PM01																								1				PKR	
0160	LEMM	0040	PM01																								1				PKR	
0170	LEMM	0040	PM01																								1				PKR	
0180	LEMM	0040	PM01																								1				PKR	
0190	LEMM	0040	PM01																								1				PKR	
0200	LEMM	0040	PM01																								1				PKR	
0210	LEMM	0040	PM01																								1				PKR	
0220	LEMM	0040	PM01																								1				PKR	
0230	LEMM	0040	PM01																								1				PKR	

MntPack Components Rel PRT SPack Insp.Chal Entry 1 / 2

U IBM PKGDVP INS

31. Click button .



Create Equipment Task List: Header General View

Equipment task list Edit Goto Task list header Extras Environment System Help

Create Equipment Task List: Header General View

Equipment 10014084 Training Material for Carton
Group 300447 Training Material for Carton

Group 300447
Group Counter 1 Training Material for Carton
Planning plant 0040

Assignments to Header

Work center LEMM / 0040 LEMANIC MAINTENANCE
Usage 4 Plant maintenance
Planner group
Status 4 Released (general)
System Condition 1 In operation
Maintenance strategy STNDRD Standard Time-Based Maint.
Assembly
☐ Deletion flag

OM Data

Inspection points
Ext. numbering Unique external numbering possible

U IBM PKGDVP INS

32. Click button .

[illegible]